

Witness inspection report

LARGE BUTTERFLY VALVES (VF264/SA10)

Manufacturer: Value Valves Co., Ltd.

Customer: BVC

Client: Siemens PG

Job No.: 7026-1 (4500548849)

KKS: 10PAB11AA001/10PAB12AA001/10PAB21AA001/10PAB22AA001/10PAB31AA001/10PAB32AA001

Test Location: Value Valves Co., Ltd. Test Field, Taipei, Taiwan

Participants; David Chen/ Deputy Gen.Manager of Value Valves Co., Ltd.

Wallace Lan/QA Team Chief of Value Valves Co., Ltd.

Eric Lee/Sales Team of Value Valves Co., Ltd.

QE/Inspector: Dan Ruppert/WonHwal, Lee

Date: 20~22 January, 2009

Contents;



1 Check List; Attached



Check list img-128083945.zip

2.0 Inspection Photography;

2-1 Dimension Inspection.




Siemens Ltd.


Asia Tower

726 Yeoksam-dong

Kangnam-ku, Seoul/Korea 135-080

2-2 Visual Inspection.





2-3 Performance Inspection (Actuator Valve & Geared Valve).



2-4 Hydrostatic Test for Body (Actuator Valve).



2-5 Hydrostatic Test for Body (Geared Valve).



2-6 Leakage Test for Seat (Actuator Valve).


Siemens Ltd.
Asia Tower
726 Yeoksam-dong
Kangnam-ku, Seoul/Korea 135-080



2-7 Leakage Test for Seat (Geared Valve).



2-8 Painting Inspection.



Location Factory (Value Valves Co., Ltd.)



==End==